

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/25/2018

Submitted Date:

08/20/2018

Document Number:

680602924**FIELD INSPECTION FORM**Loc ID 427218 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10515Name of Operator: GUNNISON ENERGY LLCAddress: 1801 BROADWAY #1200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Cleary, Mike		mike.cleary@oxbow.com	
McWilliams, Dan	(970) 986-2927	dan.mcwilliams@oxbow.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427223	WELL	PR	08/12/2013	GW	051-06103	DGU Hotchkiss Federal 1289 18-H1	RI
427241	WELL	PR	11/15/2012	GW	051-06104	DGU Hotchkiss Federal 1289 18-H2	RI
436491	WELL	XX	09/01/2016	LO	051-06120	DMGU 1289 18-H4	RI
436492	WELL	XX	09/01/2016	LO	051-06121	DMGU 1289 18-H3	RI
436613	WELL	WO	08/21/2014	LO	051-06124	DGU Federal 1289 18-CS2	RI
436614	WELL	WO	08/13/2014	LO	051-06125	DGU Federal 1289 18-CS1	RI
436921	WELL	XX	09/01/2016	LO	051-06131	DMGU 1289 18-H5	RI

General Comment:

This is a followup inspection for inspection number 680602136 conducted on October 19, 2017. A field inspection was conducted on July 25, 2018 and followed up with a desktop review on August 20, 2018. Gunnison Energy has submitted a variance request to delay interim reclamation at this location, that is currently under review. Any corrective actions not addressed from previous inspections are still applicable.

Inspected Facilities				
Facility ID: <u>427223</u>	Type: <u>WELL</u>	API Number: <u>051-06103</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>427241</u>	Type: <u>WELL</u>	API Number: <u>051-06104</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>436491</u>	Type: <u>WELL</u>	API Number: <u>051-06120</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>436492</u>	Type: <u>WELL</u>	API Number: <u>051-06121</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>436613</u>	Type: <u>WELL</u>	API Number: <u>051-06124</u>	Status: <u>WO</u>	Insp. Status: <u>RI</u>
Facility ID: <u>436614</u>	Type: <u>WELL</u>	API Number: <u>051-06125</u>	Status: <u>WO</u>	Insp. Status: <u>RI</u>
Facility ID: <u>436921</u>	Type: <u>WELL</u>	API Number: <u>051-06131</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: Revegetation is progressing within the outer revegetation areas, although weedy in portions of the berm and fill slopes.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Musk thistles appear to have recently received herbicide treatment within the outer revegetation areas. However, untreated rosettes remain. Subsequent treatments and monitoring will be needed.

Corrective Action Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>
---------------------------	--	--

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater erosion appears to be controlled at this time.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680602925	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555415