

Inspection Photos

Operator: Gunnison Energy

API: 05-051-06126

Date: 7/25/2018



Photo 1. View of the project area from the northeastern edge facing center.



Photo 2. View of the northern portion of the project area from the northeastern edge facing westward.



Photo 3. View of the eastern portion of the northeastern edge facing southward.



Photo 4. View of the southwestern portion of the project area facing southward. Some revegetation is progressing through erosional blankets.



Photo 5. View of the southern portion of the project area from the southwestern corner facing eastward. Silt trap appears to be functioning.