

# Inspection Photos

08/14/2018

Operator: PRONGHORN OPERATING LLC - 10422

Location ID: 387156

Inspection Doc. Number: 682503737

Lincoln County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: PRONGHORN OPERATING LLC - 10422  
Location ID: 387156



**Photo 1:** Photo taken from the south end of the location, facing west. Photos 1-4 provide an overview of the location, facing west, northwest, northeast, to east. Photo shows the reclamation area. Location remains predominantly bare and exposed soil. Vegetation observed predominantly undesirable weedy plant species. Unable to find evidence of work conducted per corrective actions.

Inspection Photos  
Operator: PRONGHORN OPERATING LLC - 10422  
Location ID: 387156



**Photo 2:** See comments under photo 1.



**Photo 3:** See comments under photo 1.

Inspection Photos  
Operator: PRONGHORN OPERATING LLC - 10422  
Location ID: 387156



**Photo 4:** See comments under photo 1.

Inspection Photos  
Operator: PRONGHORN OPERATING LLC - 10422  
Location ID: 387156



**Photo 5:** Photo taken from the north end of the location, facing northeast. Previous inspection documented pipe equipment remaining on location and required it to be removed. Photo shows pipe remains on location.



**Photo 6:** Photo taken from the north end of the location, facing south. Previous inspection documented equipment/trash debris remaining on location and required it to be removed. Photo shows equipment/trash debris remains on location.



**Photo 7:** Photo taken from the west end of the location, facing east. Photo shows the reclamation area. Location remains predominantly bare and exposed soil. Vegetation observed predominantly undesirable weedy plant species. Unable to find evidence of work conducted per corrective actions.



**Photo 8:** Photo taken from the central area of the location, facing north. Photo shows 1 of the 2 germination surveys conducted on the location.



**Photo 9:** Photo taken from the midpoint of the germination survey. Photo shows location is mostly bare and exposed soil, and vegetation over the reclamation area is predominantly undesirable weedy plant species.



**Photo 10:** Photo taken from the midpoint of the germination survey. Survey shows location has an average germination of 0.8 seedlings per  $\frac{1}{2}$  m<sup>2</sup>, or 0.148 seedlings per square foot.



**Photo 11:** Photo taken from the north end of the location, facing south. Photo shows 2 of the 2 germination surveys conducted on the location. Survey 1 ran north/south in the middle of the location and Survey 2 ran east/west in the middle of the location. Surveys intersected at the 50<sup>th</sup> point (“+”)