

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/22/2018

Submitted Date:

08/22/2018

Document Number:

691200358**FIELD INSPECTION FORM**
 Loc ID 331151 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
		regulatory@foundationenergy.com	All Inspections
Peter Cowan		picowan@blm.gov	BLM; federal/federal inspections
		vkoehler@fs.fed.us	USFS; federal/federal inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258930	WELL	PR	06/28/2001	GW	123-20234	FEDERAL TOUCAN 28-14	PR

General Comment:

This is a WELL Inspection. For Battery Inspection info refer to FIR #691200356.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign label is faded or peeling. Signs and Markers General Condition. Sign not legible. Install sign to comply with Rule 210.e.			
Corrective Action:	Comply with Rule 210.e.			Date: 10/22/2018
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Barbed wire			
Corrective Action:				Date:
Type	PUMP JACK			
Comment:	Iron mesh panel			
Corrective Action:				Date:
Equipment:				
			corrective date	
Type: Prime Mover	# 1			
Comment:	Gas Engine. Stained soil in engine house appears to have been remediated addressing the CA form FIR #684903928 dated 7/27/2017.			
Corrective Action:				Date:
Type:	#			
Comment:	Refer to FIR #691200356 for additional equipment details.			
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:	3 / 4. 1 anchor is bent over and unmarked. Mark guy line anchors per Rule 604.c.(2)Q. Any CA(s) form previous FIRs that have not been addressed are still applicable. The original CA date still applies.			
Corrective Action:	Comply with Rule 604.c.(2)Q.			Date: 08/04/2017

Type: Compressor	# 1		
Comment:	At wellhead. Has drip tray.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Stained soil at wellhead appears to have been remediated addressing the CA form FIR #684903928 dated 7/27/2017.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.626209,-104.107827	
Comment:	This centralized battery services 3 locations (305200, 331082, 331151). Refer to FIR #691200356 for Tanks & Berms details.					
Corrective Action:		Date:				

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	258930	Type:	WELL	API Number:	123-20234	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR.							
Corrective Action:								Date:	
BradenHead									
Comment:		Bradenhead appears plumbed to surface.							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: <input type="text"/>	Other: <input type="text"/>	Length: <input type="text"/>	Width: <input type="text"/>	

Lining:

Liner Type:

Liner Condition:

Comment: [Refer to FIR #691200356 for pit information.](#)

Corrective Action

Date: **Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date: **Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200359	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4559383