

## Inspection Photos

Location Name: D.O.C. Showers - 68N60W / 32NWSW

Location #: 330667



**Photo #1**

**D.O.C. Showers 32-12-10** (API # 05-123-19437)  
wellhead



**Photo #2**

**D.O.C. Showers 32-12-10, Showers 32-5-7**  
Battery



## Inspection Photos

Location Name: D.O.C. Showers - 68N60W / 32NWSW

Location #: 330667



**Photo #3**

***D.O.C. Showers 32-12-10 , Showers 32-5-7***

Treater house

*From previous FIR*



**Photo #4**

***D.O.C. Showers 32-12-10 , Showers 32-5-7***

Treater house

***Muddy floor, No hydrocarbons, no leaks***



## Inspection Photos

Location Name: D.O.C. Showers - 68N60W / 32NWSW

Location #: 330667



**Photo #5**

***D.O.C. Showers 32-12-10 , Showers 32-5-7***

H2O tank – stained soil

*From previous FIR*



**Photo #6**

***D.O.C. Showers 32-12-10 , Showers 32-5-7***

H2O tank – stained soil

**Soil stains mitigated, New capacity label prep for stencil**



## Inspection Photos

Location Name: D.O.C. Showers - 68N60W / 32NWSW

Location #: 330667



**Photo #7**

***D.O.C. Showers 32-12-10 , Showers 32-5-7***

H2O tank – low berms

*From previous FIR*



**Photo #8**

***D.O.C. Showers 32-12-10 , Showers 32-5-7***

H2O tank – berms

**Berms are inadequate**



## Inspection Photos

Location Name: D.O.C. Showers - 68N60W / 32NWSW

Location #: 330667



**Photo #9**

***D.O.C. Showers 32-12-10 , Showers 32-5-7***

**2 - Unmarked risers**



**Photo #10**

***D.O.C. Showers 32-12-10 , Showers 32-5-7***

**Scrubber sump**



## Inspection Photos

Location Name: D.O.C. Showers - 68N60W / 32NWSW

Location #: 330667



**Photo #11**

***D.O.C. Showers 32-12-10 , Showers 32-5-7***

**Closed Pit area**

