

GM 236-34
API# 05-045-07640
Inspection# 689701746



Well photo.

GM 236-34
API# 05-045-07640
Inspection# 689701746



Weeds and storm water on location

GM 236-34
API# 05-045-07640
Inspection# 689701746



08.23.2018 11:28



08.23.2018 11:28

Weeds and storm water on location

Weeds and storm water on location

GM 236-34
API# 05-045-07640
Inspection# 689701746



08.23.2018 11:31



08.23.2018 11:31

Culvert inside of location wall unclear of status.

Culvert inside of location wall unclear of status.

GM 236-34
API# 05-045-07640
Inspection# 689701746



Culvert outside of location wall unclear of status.

GM 236-34
API# 05-045-07640
Inspection# 689701746



08.23.2018 11:38



08.23.2018 11:38

Damaged bales north east of location in drainage.

GM 236-34
API# 05-045-07640
Inspection# 689701746



Weeds and weed debris in culvert basin on main road.