

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2018

Submitted Date:

08/24/2018

Document Number:

688500079**FIELD INSPECTION FORM**Loc ID 319709 Inspector Name: CANFIELD, CHRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Oakman, Kari		kari.oakman@state.co.us	
Brown, Devin	(303)-349-0302	dbrown@petrosharecorp.com	Production Ops Manager
Axelson, John		john.axelson@state.co.us	
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201052	WELL	SI	06/01/2017	OW	001-06455	STATE OF COLORADO AB 1	SI
319709	LOCATION	AC			-	STATE OF COLORADO AB-62S66W 16NESE	EI
445292	TANK BATTERY	AC	03/30/2016		-	State of Colorado AB Tank Battery	AC

General Comment:

Inspection of Location ID 319709 to gauge the operator's progress on REM 11710 (concerning Spill/Release 453361) and REM 11714 (concerning closure of a partially-buried vessel).

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	See the attached photo log for multiple examples of weeds growing at the subject location.		
Corrective Action:	Comply with Rule 603.f	Date:	09/07/2018
Type	UNUSED EQUIPMENT		
Comment:	See Photo 5 for an example of unusead equipment observed at the subject location.		
Corrective Action:	Comply with Rule 603.f	Date:	09/21/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	See photos 6, 7, & 8 for examples of open excavations without temporary safety fencing		
Corrective Action:	Per Rule 605.c, temporary safety fencing is required to protect public safety.	Date:	08/31/2018
Type	LOCATION		
Comment:	Perimeter fence has been removed from the south side of the location (see photos 2,3, & 4).		
Corrective Action:	Fencing required on the south side of the subject location to restrict access by unauthorized persons.	Date:	08/31/2018

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 319709 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:**Comment:** _____

Corrective Action: _____

Date: _____

Wildlife BMPs:**Comment:** _____

Corrective Action: _____

Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
_____	_____	_____	_____

Comments: Erosion BMPs: [See photos 4, 9, 10, & 11 for examples of spoil piles without storm-ware BMPs](#)

Other BMPs: _____

Corrective Action: **Install storm-water BMPs as required by Rule 1002.f.**Date: **08/31/2018****Comment:** _____**Corrective Action:** _____

Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	<u>201052</u>	Type:	<u>WELL</u>	API Number:	<u>001-06455</u>	Status:	<u>SI</u>	Insp. Status:	<u>SI</u>
Facility ID:	<u>319709</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>445292</u>	Type:	<u>TANK</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>AC</u>

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: _____

Comment: Impacted materials apparently excavated.

Corrective Action: Submit laboratory analysis of confirmation samples. Submit manifests, haul tickets, & gate tickets for all loads of impacted material transported offsite for disposal.

Date: 09/07/2018

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment

User

Date

Inspection of Location ID 319709 to gauge the operator's progress on REM 11710 (concerning Spill/Release 453361) and REM 11714 (concerning closure of a partially-buried vessel).

canfielc

08/24/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688500080	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4561126