

Inspection Photos
Location Name: Falcon Seaboard 11-90-11 #2
API: 05-051-06061



Stained soil near well head.



Remnants of liner.

Inspection Photos
Location Name: Falcon Seaboard 11-90-11 #2
API: 05-051-06061



Frac tanks used for drilling fluid during drilling operations.



Scraps of liner from closed loop cuttings management area.

Inspection Photos
Location Name: Falcon Seaboard 11-90-11 #2
API: 05-051-06061



Various equipment leaks throughout location.



Falcon Seaboard 11-90-11 #2 tank battery.