

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/17/2018

Submitted Date:

08/18/2018

Document Number:

691200347

**FIELD INSPECTION FORM**

Loc ID 306577 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 76840  
Name of Operator: SCHNEIDER ENERGY SERVICES INC  
Address: P O BOX 889  
City: FORT MORGAN State: CO Zip: 80701

**Findings:**

- 14 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Schneider, Jeff	970-867-9437	jeff@schneiderenergy.com	President
Pesicka, Conor		conor.pesicka@state.co.us	
Bothwell, Kevin	970-867-9437	kevin@schneiderenergy.com	Vice-President

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289838	WELL	PR	03/01/2018	OW	123-24938	DRYER 1	SI

**General Comment:**

Empty text area for general comments.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign has been posted at wellhead which addresses the CA from previous FIR #684902409.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	55-gal. Drum, labeling / placard appears illegible.		
Corrective Action:	Comply with Rule 210.e using the Rule 210.e guidance document for further details.		Date: 10/19/2018
Emergency Contact Number:			
Comment:	Emergency contact info has been posted at wellhead which addresses the CA from previous FIR #684902409.		
Corrective Action:			Date:
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused pump jack belt guard.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 09/19/2018
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Heavy iron mesh		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type:	#		

Comment:	Refer to FIR #691200345 for additional equipment details.	Date:	
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Stained soil at wellhead & near pump jack appears to have been remediated. Thich addresses the CA from previous FIR #684902409. Gearbox appears to have stain and seepage.	Date:	09/19/2018
Corrective Action:	Remediate stained equipment; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.	Date:	09/19/2018
Type: Prime Mover	# 1		
Comment:	Gas engine (Ajax). Stained soil appears near engine base.	Date:	09/19/2018
Corrective Action:	Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.	Date:	09/19/2018

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.577190,-104.066593
Comment:	This centralized battery services 2 location ID's. (317498, 306577). Refer to FIR #691200345 for Tanks & Berms details.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	Date:	
Comment:	Observed wellhead stuffing box venting with loud audible hissing. Operator President Jeff Schneider met COGCC field inspector Bret Evins on adjacent April 12-14 location at approximately 2:30pm today. Mr. Schneider informed me that he would make mechanical adjustments to stop the venting immediately.		
Corrective Action:		Date:	

**Flaring:**

Type		Date:	
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 289838 Type: WELL API Number: 123-24938 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Observed well was shut-in with valves closed at wellhead. Pump jack and engine were also shut-down.  
Operator President Jeff Schneider met COGCC field inspector Bret Evins on adjacent April 12-14 location at approximately 2:30pm today. He disclosed that well would be SI until separator can be replaced.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead does NOT appear plumbed to surface.

Corrective Action: **Plumb bradenhead to surface; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.** Date: 09/19/2018

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401737332	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555402">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555402</a>
691200348	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555399">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555399</a>