

**FORM
INSP**Rev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/17/2018

Submitted Date:

08/20/2018

Document Number:

689401543**FIELD INSPECTION FORM**

Loc ID 312634 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10150Name of Operator: BLACK HILLS PLATEAU PRODUCTION LLCAddress: 1515 WYNKOOP ST STE 500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Laramie Energy LLC		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222064	WELL	PR	09/01/2017	GW	077-08666	OXBOW 18-1E	PR

General Comment:

[This is a follow up inspection to FIR Doc#689401520 in response to FIRR Doc#401735152. Any corrective actions not addressed from previous inspections are still applicable.](#)

Location

Lease Road:			
Type	Access		
comment:	See housekeeping section of inspection.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	Posted Emergency Contact Number 1-800-891-6191	
Corrective Action:		Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Halogeton, C List Noxious Weed, along access road. Weeds did not appear to have been addressed. Original corrective action and date still apply.		
Corrective Action:	Comply with the 1003. f	Date:	08/15/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Pit ID#112373 used as tank containment.			
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 222064	Type: WELL	API Number: 077-08666	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing at time of inspection			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater controls have been installed along roadway and on edge of location. See attached photos. Corrective action from previous inspection has been met.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401737484	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555422
689401544	Oxbow 18-1E Follow up photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4555421