

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401745430

Date Received:  
08/27/2018

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Recipient, Single

Inspections@catamountep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602786

Inspection Date: 06/18/2018

FIR Submit Date: 07/03/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 333779

Location Name: JACQUES-N33N8W Number: 27NWNE County: LA PLATA

Qtrqr: NWNE Sec: 27 Twp: 33N Range: 8W Meridian: N

Latitude: 37.079390 Longitude: -107.701180

FACILITY - API Number: 05-067- -00 Facility ID: 214670

Facility Name: JACQUES Number: 3

Qtrqr: NWNE Sec: 27 Twp: 33N Range: 8W Meridian: N

Latitude: 37.079390 Longitude: -107.701180

CORRECTIVE ACTIONS:

**1** CA# 117185

Corrective Action: Remove debris.

Date: 07/17/2018

Response: CA COMPLETED

Date of Completion: 07/13/2018

Operator  
Comment:

Removed metal debris, orange fencing and chunks of cement from location.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 117186

Corrective Action: Remove unused equipment.

Date: 09/03/2018

Response: CA COMPLETED

Date of Completion: 07/25/2018

Operator  
Comment: Removed equipment from location.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**3** CA# 117187

Corrective Action: Erosion and stormwater controls need to be installed on the well pad cut-slope and in the southeastern portion of the project area where diverted stormwater exits the well pad.

Date: 08/03/2018

Response: CA COMPLETED

Date of Completion: 07/25/2018

Operator  
Comment: Resloped the cut slope, installed a rock rundown in the South East corner of the location

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed: \_\_\_\_\_

Title: Geo/Eng Tech

Date: 8/27/2018 2:24:27 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401745435	Remedial Report
-----------	-----------------

401745449	Remedial Report
-----------	-----------------

Total Attach: 2 Files