

Inspection Photo
Encana FEE 10-2D
API # 045-20395
Inspection # 689301832



Location Photo #1



Location Photo #2

**Inspection Photo
Encana FEE 10-2D
API # 045-20395
Inspection # 689301832**



**Location Photo #3, stained ground by back of
blowdown tank.**



**Location Photo #4, Weeds near wellhead and
blowdown tank.**

Inspection Photo
Encana FEE 10-2D
API # 045-20395
Inspection # 689301832



Location Photo #5, Weeds near welheads

