

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/21/2018

Submitted Date:

08/21/2018

Document Number:

689301788**FIELD INSPECTION FORM**
 Loc ID 335551 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1600 BROADWAY ST STE 2600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293336	WELL	PR	10/01/2017	GW	045-14947	DEVER C9	PR
293337	WELL	PR	11/06/2007	GW	045-14946	DEVER C8	PR
293338	WELL	PR	12/24/2013	GW	045-14945	Dever C7	PR
293341	WELL	PR	05/01/2018	GW	045-14942	DEVER C4	PR
293342	WELL	PR	05/01/2018	GW	045-14941	DEVER C3	PR
293343	WELL	XX	03/12/2018	LO	045-14940	Dever C2	ND

**General Comment:**[Routine Field inspection](#)

Location					
<b>Lease Road:</b>					
Type	Access				
comment:					
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:	1-855-625-9922				
Corrective Action:					Date:
<b>Good Housekeeping:</b>					
Type	WEEDS				
Comment:	Weeds along access road				
Corrective Action:	Comply with Rule 603.f .				Date: 08/31/2018
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing/:</b>					
Type	WELLHEAD				
Comment:	Livestock gates				
Corrective Action:					Date:
<b>Equipment:</b>					
					corrective date
Type: Ancillary equipment	# 1				
Comment:	Chemical unit at wellhead				
Corrective Action:					Date:
Type: Bird Protectors	# 5				
Comment:					
Corrective Action:					Date:
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 6				
Comment:					
Corrective Action:					Date:
Type: Emission Control Device	# 1				
Comment:					
Corrective Action:					Date:

Type: Flow Line	# 1	
Comment:	water lines	
Corrective Action:		Date:
Type: Deadman # & Marked	# 3	
Comment:	Unmarked anchor	
Corrective Action:	Mark as required	Date: 09/21/2018

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		,
Comment:	3 out of service Centralized battery				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Containment damage, see photo			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 09/21/2018

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	293336	Type:	WELL	API Number:	045-14947	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	293337	Type:	WELL	API Number:	045-14946	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	293338	Type:	WELL	API Number:	045-14945	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	293341	Type:	WELL	API Number:	045-14942	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	293342	Type:	WELL	API Number:	045-14941	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	293343	Type:	WELL	API Number:	045-14940	Status:	XX	Insp. Status:	ND

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
				Material Handling And Spill Prevention		
		Compaction				
		Gravel				
Seeding						
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401739989	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4558264">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4558264</a>
689301789	Inspection photo 689301789	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4558257">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4558257</a>