

Inspection Photos  
Location Name: Pinnacle Unit 12-30  
API: 05-103-05906



**Photo 1. Overview of location taken at entrance facing south.**



**Photo 2. No tank label, overflow leading to soil staining.**

Inspection Photos  
Location Name: Pinnacle Unit 12-30  
API: 05-103-05906



**Photo 3. Stained soil in tank battery berm.**



**Photo 4. Close up of Photo 3.**

Inspection Photos  
Location Name: Pinnacle Unit 12-30  
API: 05-103-05906



**Photo 5. Stained soil at pump jack exhaust.**



**Photo 6. Stained soil at wellhead.**



Inspection Photos  
Location Name: Pinnacle Unit 12-30  
API: 05-103-05906



**Photo 7. Rods and tubing stored on location.**



**Photo 8. Soil staining under stored tubing.**