

GR 23-34
API# 05-045-06640
Inspection# 689701751



Well photo.

GR 23-34
API# 05-045-06640
Inspection# 689701751



Tank capacity is blank.

GR 23-34
API# 05-045-06640
Inspection# 689701751



Erosion and movement of sediment

GR 23-34
API# 05-045-06640
Inspection# 689701751



Erosion and movement of sediment

GR 23-34
API# 05-045-06640
Inspection# 689701751



Sediment built up in ditch

GR 23-34
API# 05-045-06640
Inspection# 689701751



Unused fence materials.



Unmarked deadman

GR 23-34
API# 05-045-06640
Inspection# 689701751



Check dam built up with sediment.



Sediment leaving check dam.

GR 23-34
API# 05-045-06640
Inspection# 689701751



Diversion ditch built up with sediment.

Sediment washing over ditch.

GR 23-34
API# 05-045-06640
Inspection# 689701751



Culvert has dead weed debris

GR 23-34
API# 05-045-06640
Inspection# 689701751



Road ditch needs maintained



Sediment flow over road way