

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/22/2018

Submitted Date:

08/29/2018

Document Number:

692400058**FIELD INSPECTION FORM**

Loc ID 456353 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoila ndgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456353	LOCATION	AC	07/27/2018		-	G09 Frac Pad	CI

General Comment:

This is a Construction and Stormwater Inspection. Form 42 : NOTICE OF CONSTRUCTION: was Filed for this Site, Start Date 8/11/2018. Conditions at time of Inspection were Clear Sunny Skies, at 75 degrees F. Elevation at Site is 7,666 ft.

Location Construction

Location ID: 456353 CDP: _____

Comment: This Construction is for remote frac pad to support completion of wells on adjacent well pads. Site is to be fully reclaimed once completion activities are finished. At time of Inspection no equipment was working; hydro axing of several acres of site was only work completed. Operator indicated that Construction of this site is under company review & may be cancelled.

Corrective Action: _____

Date: _____**Form 2A COAs:****Comment:** _____

Corrective Action: _____

Date: _____**Wildlife BMPs:****Comment:** Site is within a Sensitive Wildlife Habitat Area; Greater Sage Grouse & CPW Black Bear Area.

Corrective Action: _____

Date: _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
WADDLES	Yes		

Comments: Erosion BMPs: Wattles installed on downgradient perimeter of site have been disturbed and damaged by Cattle. If it is decided to Abandon construction of Location, Wattles will be removed & utilized at adjacent locations.

Other BMPs: _____

Corrective Action: _____

Date: _____**Comment:** Distance to Nearest downgradient surface water feature, West fork Parachute Creek, is 252 feet.**Corrective Action:** _____**Date:** _____**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

