

Inspection Photos

Loc#335699

Operator: Caerus

Inspection Number: 692400057

Inspection Date: 8/22/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest.

August 22, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus NPR G09 Loc#335699



Photo#2:
Overview of Location from top of cut slope to Northwest.

August 22, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus NPR G09 Loc#335699



Photo#3:

Topsoil windrowed along toe of Fill slope is not being protected / segregated as required by the reclamation rules.

August 22, 2018



Photo#4:



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus NPR G09 Loc#335699



Photo#5:
BMPs have been installed around Location Perimeter



Photo#6:
Some Wattles are not properly seated in.

August 22, 2018



Photo#7:

Well Cellars do not have covers installed.

August 22, 2018



Photo#8:

One Well head (API#045-13007) was bubbling/leaking.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus NPR G09 Loc#335699