

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2018

Submitted Date:

08/29/2018

Document Number:

691200390**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 332130 Evins, Bret 2A Doc Num: _____

Operator Information:OGCC Operator Number: 70385Name of Operator: SMITH ENERGY CORPAddress: 12706 SHILOH RDCity: GREELEY State: CO Zip: 80631**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
Smith, Glenn	(970) 381-6253	gsmithten@what-wire.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270349	WELL	SI	06/01/2018	GW	123-21877	NORTHRUP 2-14	SI

General Comment:[This is a WELL Inspection. Refer to FIR #691200386 for Battery Info.](#)

Location					
Lease Road:					
Type	Access				
comment:	Access road has some weed overgrowth. 2-Track Ag road.				
Corrective Action	L			Date:	
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:					
Corrective Action:					Date: _____
Good Housekeeping:					
Type	WEEDS				
Comment:	Weeds around wellhead area. Statewide unused equipment, weeds, waste, and trash requirements. 10 days for weeds. Refer to Rule 603.f for guidance.				
Corrective Action:	Comply with Rule 603.f .			Date:	09/10/2018
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:					
Type:		#		corrective date	
Comment:	Refer to FIR #691200386 for additional Equipment info.				
Corrective Action:				Date:	
Type: Plunger Lift		# 1			
Comment:					
Corrective Action:				Date:	
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.575290,-103.726730
Comment:	This Centralized Battery services 3 Locations (327106, 305168, 332130). Refer to FIR #691200386 for additional Tanks & Berms info.				
Corrective Action:				Date:	
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	

Comment:					
Corrective Action:					Date:
<u>Venting:</u>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 270349 Type: WELL API Number: 123-21877 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI. Records indicate SI since 6/2018. Appears to not be producing.

Corrective Action: _____ Date: _____

BradenHeadComment: Bradenhead does NOT appear plumbed to surface. Plumb bradenhead to surface. 30 days.
Mechanical Conditions
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition,
inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.Corrective Action: Comply w/ Rule 605.d. Date: 09/28/2018

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200392	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4565914