

Inspection Photos
Location Name: Diemoz A3
API: 05-045-19924



Location Entry



Location Entry

Inspection Photos
Location Name: Diemoz A3
API: 05-045-19924



Weeds on the East Side of location



Weeds at the west side of location

Inspection Photos
Location Name: Diemoz A3
API: 05-045-19924



Location used for storage



Location used for storage

Inspection Photos
Location Name: Diemoz A3
API: 05-045-19924



Debris around well head, inside cellar. Tire is inside of this cellar.



Open Bore hole with debris covering

Inspection Photos
Location Name: Diemoz A3
API: 05-045-19924



Weed along lease road



Weed along lease road