

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2018

Submitted Date:

08/24/2018

Document Number:

688500079

**FIELD INSPECTION FORM**

Loc ID 319709 Inspector Name: CANFIELD, CHRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10454  
Name of Operator: PETROSHARE CORPORATION  
Address: 9635 MAROON CIRCLE #400  
City: ENGLEWOOD State: CO Zip: 80112

**Findings:**

- 10 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Brown, Devin	(303)-349-0302	dbrown@petrosharecorp.com	Production Ops Manager
Oakman, Kari		kari.oakman@state.co.us	
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201052	WELL	SI	06/01/2017	OW	001-06455	STATE OF COLORADO AB 1	SI
319709	LOCATION	AC			-	STATE OF COLORADO AB-62S66W 16NESE	EI
445292	TANK BATTERY	AC	03/30/2016		-	State of Colorado AB Tank Battery	AC

**General Comment:**

Inspection of Location ID 319709 to gauge the operator's progress on REM 11710 (concerning Spill/Release 453361) and REM 11714 (concerning closure of a partially-buried vessel).

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	See Photo 5 for an example of unusaed equipment observed at the subject location.		
Corrective Action:	Comply with Rule 603.f	Date:	09/21/2018
Type	WEEDS		
Comment:	See the attached photo log for multiple examples of weeds growing at the subject location.		
Corrective Action:	Comply with Rule 603.f	Date:	09/07/2018

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	See photos 6, 7, & 8 for examples of open excavations without temporary safety fencing		
Corrective Action:	Per Rule 605.c, temporary safety fencing is required to protect public safety.	Date:	08/31/2018
Type	LOCATION		
Comment:	Perimeter fence has been removed from the south side of the location (see photos 2,3, & 4).		
Corrective Action:	Fencing required on the south side of the subject location to restrict access by unauthorized persons.	Date:	08/31/2018

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Location Construction**

Location ID: 319709 CDP: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:**

Corrective Action:  Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

Corrective Action:  Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Comments: Erosion BMPs: [See photos 4, 9, 10, & 11 for examples of spoil piles without storm-ware BMPs](#)

Other BMPs:

Corrective Action: **Install storm-water BMPs as required by Rule 1002.f.** Date: **08/31/2018**

**Comment:**

**Corrective Action:**  Date: \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: 201052 Type: WELL API Number: 001-06455 Status: SI Insp. Status: SI

Facility ID: 319709 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Facility ID: 445292 Type: TANK API Number: - Status: AC Insp. Status: AC

**Environmental**

**Spills/Releases:**

Type of Spill: OIL Estimated Spill Volume: \_\_\_\_\_

Comment: Impacted materials apparently excavated.

Corrective Action: Submit laboratory analysis of confirmation samples. Submit manifests, haul tickets, & gate tickets for all loads of impacted material transported offsite for disposal. Date: 09/07/2018

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
Inspection of Location ID 319709 to gauge the operator's progress on REM 11710 (concerning Spill/Release 453361) and REM 11714 (concerning closure of a partially-buried vessel).	canfielc	08/24/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401743255	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4561127">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4561127</a>
688500080	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4561126">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4561126</a>