

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/31/2018

Submitted Date:

08/24/2018

Document Number:

688800259**FIELD INSPECTION FORM**

Loc ID 414132 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Findings:**14 Number of Comments1 Number of Corrective Actions

- 
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		inspection@sginterests.com	<a href="#">All Inspections</a>
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413159	WELL	PR	06/30/2015	GW	051-06094	COW SKULL 11-89-18 1	EI
422989	WELL	PR	05/21/2017	GW	051-06100	Cow Skull 11-89-18 2	EI

**General Comment:**

On July 31, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Cow Skull 11-89-18 #1 and #2. For the most recent field inspection report of this facility, please refer to document #689400875. An SGI employee was on site during this field inspection.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Both well heads have signs nearby. The sign for the #2 was laying on the ground during this inspection.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Tubing on rack in NW corner of location.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Lube Oil		<= 1 bbl	
Comment:	Stained soil near drain outlet for skid mounted compressor. SGI employee on site stated that he would remove the stained soil while on location.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>09/24/2018</u>
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Plunger Lift	# 1		corrective date
Comment:	Cow Skull 11-89-18 #1 well head.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Dismantled at the time of this inspection. Natural gas powered.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Valve can and chemical injection system in SE corner of location, near entrance.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Skid mounted compressor.		

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLs	HEATED STEEL AST		39.098791,-107.380737
Comment:	Drop out tanks for heater gas supply appear to have been blown down on the gravel.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Lined steel ring.			
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 413159 Type: WELL API Number: 051-06094 Status: PR Insp. Status: EI

Facility ID: 422989 Type: WELL API Number: 051-06100 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for chemical containers.

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On July 31, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Cow Skull 11-89-18 #1 and #2. For the most recent field inspection report of this facility, please refer to document #689400875. An SGI employee was on site during this field inspection.</p> <p>A tubing rack full of tubing is being stored in the NW corner of the location.</p> <p>The drop out tanks for the AST heaters are being blown down onto the gravel. Use a drip pan or other device when removing water from the tanks.</p> <p>The drain outlet for the skid mounted compressor has stained soil beneath it. SGI employee on site stated that he would remove the stained soil while on location.</p>	hughesj	08/24/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401743871	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4561533">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4561533</a>
688800260	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4561531">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4561531</a>