

# Inspection Photos

08/29/2018

Operator: WHITING OIL & GAS CORPORATION -  
96155

Location ID: 436874

Inspection Doc. Number: 682503794  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: WHITING OIL & GAS CORPORATION - 96155  
Location ID: 436874



**Photo 1:** Photo taken from the southeast end of the interim areas, facing west.



**Photo 2:** Photo taken from the northeast end of the interim areas, facing west.



Inspection Photos  
Operator: WHITING OIL & GAS CORPORATION - 96155  
Location ID: 436874



**Photo 3:** Photo taken from the interim area. Vegetation within the interim areas appear to be predominantly undesirable weedy plant species. However, desirable perennial vegetative germination is evident within the understory. Advise weed management to facility desirable vegetative establishment.



**Photo 4:** Photo taken from the northeast end of the location, facing east. Photos 4-6 provide an overview of the location from east, to southeast, to south.



Inspection Photos  
Operator: WHITING OIL & GAS CORPORATION - 96155  
Location ID: 436874



**Photo 5:** Photo taken from the northwest corner of the location. Facing west. Photo shows interim reclamation in process. Photo also shows stormwater ditch along perimeter.



**Photo 6:** Photo taken from the north end of the location. Photo shows area where the ditch appears to have filled in over time and erosion degradation is beginning to occur. Advise maintenance to mitigate any additional disturbances.

Inspection Photos  
Operator: WHITING OIL & GAS CORPORATION - 96155  
Location ID: 436874



**Photo 7:** Photo taken from the northwest end of the location, facing east. Photo shows areas around the wells that do not appear to be reasonably needed for production activities do not appear to have been reclaimed or stabilized.



**Photo 8:** Photo taken from the northwest end of the location, facing south. Photo shows areas around the wells that do not appear to be reasonably needed for production activities do not appear to have been reclaimed or stabilized.



Inspection Photos  
Operator: WHITING OIL & GAS CORPORATION - 96155  
Location ID: 436874



**Photo 9:** Photo taken from the northeast end of the location, facing south. Photo shows areas around the wells that do not appear to be reasonably needed for production activities do not appear to have been reclaimed or stabilized.



**Photo 10:** : Photo taken from the northeast end of the location, facing west. Photo shows areas around the wells that do not appear to be reasonably needed for production activities do not appear to have been reclaimed or stabilized.



Inspection Photos  
Operator: WHITING OIL & GAS CORPORATION - 96155  
Location ID: 436874



**Photo 11:** Photo taken from the wells, photo shows berm at well no longer in proper functioning condition.



**Photo 12:** Photo taken from the wells, photo shows berm at well no longer in proper functioning condition.