

Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Photo #1
Joker 36-9-62 (API # 05-123-31719)
Sign at access road



Photo #2
Joker 36-9-62 (API # 05-123-31719)
Battery

Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Photo #3
Joker 36-9-62 (API # 05-123-31719) wellhead
Stained soil, weeds
Bradenhead not plumbed to surface
From previous FIR



Photo #4
Joker 36-9-62 (API # 05-123-31719) wellhead
Stained soil
Bradenhead not plumbed to surface

Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Photo #5
Joker 36-9-62 Oil & H2O tanks
Stain on middle tank
From previous FIR



Photo #6
Joker 36-9-62 Oil & H2O tanks
Middle tank stain removed

Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Colorado Oil & Gas Conservation Commission
40.71034, -104.27526, 1499.0m, 66°
2018/07/20 10:19:56 AM

Photo #7

Joker 36-9-62

Unused equipment, weeds
From previous FIR



Colorado Oil & Gas Conservation Commission
40.71031, -104.27526, 1495.0m, 176°
2018/08/31 11:24:59 AM

Photo #8

Joker 36-9-62

Weeds / Separator removed



Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Photo #9
Joker 36-9-62

Oily waste bucket / unused fittings



Photo #10
Joker 36-9-62

Stained soil near engine exhaust

Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Photo #11
Joker 36-9-62 Engine house
Stained soil & engine base



Photo #12
Joker 36-9-62 Treater house
Stained soil & wall

Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Photo #13
Joker 36-9-62 Candlestick Flare
Flare inlet open
From previous FIR




Photo #14
Joker 36-9-62 Candlestick Flare
Flare inlet Closed.
Venting has ceased.

Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Photo #15
Joker 36-9-62 Candlestick Flare
Disconnected ignition wire
From previous FIR



Photo #16
Joker 36-9-62 Candlestick Flare
Ignition wire remains disconnected



Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Photo #17

Joker 36-9-62 ECD

Inlet valve is shut. Not in operation.

From previous FIR



Photo #18

Joker 36-9-62 ECD

Inlet & pilot valves open. Pilot is unlit.

ECD not in operation

Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Photo #19

Joker 36-9-62 ECD Pilot Ignition
Switch is ON. Battery appears bad
From previous FIR



Photo #20

Joker 36-9-62 ECD Pilot Ignition
Switch is ON. Battery appears bad
ECD not in operation

Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Photo #21
Joker 36-9-62 Gas meter run
Valves appear partially open
From previous FIR




Photo #22
Joker 36-9-62 Gas meter run
Valves appear Closed
Unused Equip (Line pipe)

Inspection Photos
Location Name: Joker / 36-9-62
Location #: 417683



Photo #23
Joker 36-9-62 Tank berms
Weeds need cut

