

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2018

Submitted Date:

09/04/2018

Document Number:

681701078**FIELD INSPECTION FORM**Loc ID 335114 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Middleton, Brett		bmiddleton@caerusoilandgas.com	Sr. Environmental Specialist
Fischer, Alex		alex.fischer@state.co.us	
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Spencer, Stan		stan.spencer@state.co.us	
Janicek, Jake		JJanicek@caerusoilandgas.com	EHS Professional

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274073	WELL	PR	09/01/2017	GW	045-10324	PUCKETT 251-25	EI
291587	WELL	PR	03/31/2008	GW	045-14452	PUCKETT 31D-25D	EI
291588	WELL	PR	10/01/2017	GW	045-14451	PUCKETT 31C-25D	EI
291589	WELL	PR	03/31/2008	GW	045-14450	PUCKETT 31A-25D	EI

General Comment:

COGCC Environmental inspection, follow up to Remediation Project #11621. Operator representatives J. Janicek and B. Middleton were present during inspection to discuss remediation project status and closure request (eForm 27 doc #401724338). See field photos.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Well signs present at temporary tank battery, but unstable due to inadequate earthen berm construction. See photos.		
Corrective Action:	Install sign to comply with Rule 210.b. See Tanks and Berms section for additional corrective actions.	Date:	11/04/2018
Type	TANK LABELS/PLACARDS		
Comment:	Blue "PDC" tank lacks volume/content labels and NFPA placard. See photos.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	11/04/2018

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Tank battery has been dismantled as part of ongoing remediation efforts. Unused metal berm components and miscellaneous associated equipment (e.g., safety fence, hoses) stored on location. See photos.		
Corrective Action:	Comply with Rule 603.f.	Date:	12/04/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Temporary tank battery constructed with rocky earthen berm. See photos. Note: A Sundry Notice is required if operator intends to reuse cuttings for berm construction.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 10/04/2018

Inspector Name: Arauza, Steven

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLs	STEEL AST		,	
Comment:	Blue "PDC" tank lacks volume/content labels and NFPA placard. See photos. Corrective Action listed in Signs/Marker section of this report.					
Corrective Action:					Date:	
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate		
Comment:	Shared earthen berm with condensate AST.					
Corrective Action:	See Corrective Action for Condensate tank berms.				Date:	10/04/2018
Venting:						
Yes/No						
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: <u>274073</u>	Type: <u>WELL</u>	API Number: <u>045-10324</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>291587</u>	Type: <u>WELL</u>	API Number: <u>045-14452</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>291588</u>	Type: <u>WELL</u>	API Number: <u>045-14451</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>291589</u>	Type: <u>WELL</u>	API Number: <u>045-14450</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681701081	20180828 Field Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4569051