

Inspection Photos
Location Name: Fish Creek Unit 2 (8-20)
API: 05-107-06020



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. Tanks stored on location.

Inspection Photos
Location Name: Fish Creek Unit 2 (8-20)
API: 05-107-06020



Photo 3. Gunbarrel separator with no berm and stained soil at base.



Photo 4. Close-up of stained soil.

Inspection Photos
Location Name: Fish Creek Unit 2 (8-20)
API: 05-107-06020



Photo 5. Example of noxious weeds on location.



Photo 6. Unmarked risers.

Inspection Photos
Location Name: Fish Creek Unit 2 (8-20)
API: 05-107-06020



Photo 7. Unlabeled tank. Stained soil in tank berm.



Photo 8. Stained soil in tank berm.

Inspection Photos
Location Name: Fish Creek Unit 2 (8-20)
API: 05-107-06020



Photo 9. Stained soil in tank berm.



Photo 10. Stained soil in tank berm.

Inspection Photos
Location Name: Fish Creek Unit 2 (8-20)
API: 05-107-06020



Photo 11. Stained soil in tank berm.



Photo 12. Stained soil at pump jack exhaust.

Inspection Photos
Location Name: Fish Creek Unit 2 (8-20)
API: 05-107-06020



Photo 13. Stained soil at wellhead.



Photo 14. Stained soil at wellhead.

Inspection Photos
Location Name: Fish Creek Unit 2 (8-20)
API: 05-107-06020



Photo 15. Battery sign only contains 911, no operator emergency contact number.



Photo 16. Wellhead sign only contains 911, no operator emergency contact number.