

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/28/2018

Submitted Date:
09/04/2018

Document Number:
689801593

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 9006
Name of Operator: BOOCO'S CONTRACT SERVICES INC
Address: P O BOX 572
City: HAYDEN State: CO Zip: 81639

Findings:

- 16 Number of Comments
- 10 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Booco, Randy		boocosinc@aol.com	owner operator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232607	WELL	PR	05/01/2017	OW	107-06020	FISH CREEK UNIT 2 (8-20)	PR

General Comment:

Routine FIU inspection.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	<u>10/30/2018</u>
Type	WELLHEAD		
Comment:			
Corrective Action:			
Date:			
Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battery.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	<u>10/04/2018</u>
Emergency Contact Number:			
Comment:	<u>Only emergency number on location is 911.</u>		
Corrective Action:	Install sign to comply with Rule 210.	Date:	<u>10/04/2018</u>
Good Housekeeping:			
Type	WEEDS		
Comment:	Annual and noxious weeds on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	<u>09/14/2018</u>
Type	UNUSED EQUIPMENT		
Comment:	1- 2" steel riser and 2 - 1" steel riser at 40.37747, -107.16529 not marked for abandonment or LOTO. Flowline risers not LO/TO or marked are considered unused equipment.		
Corrective Action:	Comply with Rule 603.f .	Date:	<u>09/05/2018</u>
Type	STORAGE OF SUPL		
Comment:	Two unused tanks with no connections and no berms stored on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	<u>11/30/2018</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil	Tank		
Comment:	Stained soil at gunbarrel base.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>10/04/2018</u>
Crude Oil	Pump Jack		
Comment:	Stained soil at pump jack exhaust.		

Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	10/04/2018
Crude Oil	WELLHEAD		
Comment:	Stained soil at wellhead.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	10/04/2018

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	1		OTHER		40.377690,-107.165400
Comment:	Gunbarrel tank/seperator.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No berm. Stained soil at base.			
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
	1		STEEL AST		40.377420,-107.165240
Comment:					
Corrective Action:			Date:		

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				Inadequate

Comment: Stained soil leftover from spill cleanup.

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Date: 10/04/2018

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 232607 Type: WELL API Number: 107-06020 Status: PR Insp. Status: PR

Producing Well

Comment: [Pumping.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater BMPs observed. No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689801603	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4569178