

Construction and Stormwater Inspection

August 31, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 448107

Inspection Document #: 682403952

Weld County, CO

NESW Section 21 T4N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SHARON /11-21HZ
Location ID: 448107



Photo 1. Photo taken from the entrance of the well location, facing North. Vehicle tracking pad was observed at the intersection of CR42. Ditch and berm BMP has been installed around the entire perimeter of the location in conjunction with other BMPs.



Photo 2. Photo taken from the northwestern location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: SHARON /11-21HZ
Location ID: 448107



Photo 3. Photo taken from the southwest sediment trap, facing South. Sediment trap has been installed with an outlet protection device but no inlet protection.



Photo 4. Photo taken from the southwestern location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: SHARON /11-21HZ
Location ID: 448107



Photo 5. Photo taken from the southern sediment trap, facing North. Appears this was designed to be a sediment trap because of the outfall, but has not been completed.



Photo 6. Photo taken from the southeastern sediment trap, facing East. See comments under Photo 5.

Inspection Photos
Location Name: SHARON /11-21HZ
Location ID: 448107



Photo 7. Photo taken from the eastern topsoil stockpile, facing West. Topsoil has been salvaged and stored along the southern location. However, topsoil has not been stabilized and drilling operations are underway.