

Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: August 29, 2018



Photo #1 – Pit facility sign located on north side of pit.



Photo #2 – View of pit from NE corner. Note foreign debris (angular rocks) on top of pit liner.



Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: August 29, 2018



Photo #3 – Hoses stored on east side of pit, looking south.



Photo #4 – Additional equipment storage east of pit.



Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: August 29, 2018



Photo #5 – Holes observed in east pit berm liner (near anchor trench).




Photo #6 – Holes observed in SE corner of pit liner. Note absence of freeboard monitoring method around perimeter of pit.



Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: August 29, 2018



Photo #7 – Metal pipe observed inside of netting on south side of pit.



Photo #8 – Hole in liner observed on west pit berm.



Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: August 29, 2018



Photo #9 – Hoses with camlocks in direct contact with pit liner at NW corner of pit.




Photo #10 – White, ratcheted straps have enough slack to dip into pit fluids (red arrow), view from east side of pit.



Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: August 29, 2018



Photo #11 – Leak detection system on north side of pit.



Photo #12 – Pipeline manifold and unused HDPE surface pipe spool observed at NW corner of pit.



Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: August 29, 2018



Photo #13 – Capped and plugged off-location surface pipelines leading into location from NW corner, looking west. Note black HDPE surface pipeline in bottom left corner of photo is disconnected.



Photo #14 – Steel off-location surface pipelines lead from NW corner of pit toward production facility SE of location (next photo). HDPE surface line was disconnected on date of inspection.



Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: August 29, 2018



Photo #15 – Looking SE along steel off-location surface pipelines from previous photo.



Photo #16 – Array of steel ASTs used as gun barrel separators, located at NE corner of pit.



Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: August 29, 2018



Photo #17 – Unused equipment (hose with camlock, metal bucket, and cardboard box) inside of NW corner of tank battery. Per operator, Rubbermaid tub contains filter socks to be used inside of battery.



Photo #18 – Steel pipe stored on top of liner on south side of tank berm.



Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: August 29, 2018



Photo #19 – View of gun barrel tank battery from SE corner. Note only two condensate tanks on east end of battery have labels and placards.



Photo #20 – Unused equipment stored northeast of pit.

