

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
08/29/2018

Submitted Date:
08/29/2018

Document Number:
691200390

FIELD INSPECTION FORM

Loc ID 332130 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 70385
Name of Operator: SMITH ENERGY CORP
Address: 12706 SHILOH RD
City: GREELEY State: CO Zip: 80631

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Glenn	(970) 381-6253	gsmithten@what-wire.com	
Arthur, Denise		denise.arthur@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270349	WELL	SI	06/01/2018	GW	123-21877	NORTHRUP 2-14	SI

General Comment:

[This is a WELL Inspection. Refer to FIR #691200386 for Battery Info.](#)

Location

Lease Road:			
Type	Access		
comment:	Access road has some weed overgrowth. 2-Track Ag road.		
Corrective Action		Date:	

Overall Good:

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds around wellhead area. Statewide unused equipment, weeds, waste, and trash requirements. 10 days for weeds. Refer to Rule 603.f for guidance.		
Corrective Action:	Comply with Rule 603.f .		Date: <u>09/10/2018</u>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type:	#		
Comment:	Refer to FIR #691200386 for additional Equipment info.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.575290,-103.726730
Comment:	This Centralized Battery services 3 Locations (327106, 305168, 332130). Refer to FIR #691200386 for additional Tanks & Berms info.				
Corrective Action:				Date:	

Paint			
Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 270349 Type: WELL API Number: 123-21877 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI. Records indicate SI since 6/2018. Appears to not be producing.

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead does NOT appear plumbed to surface. Plumb bradenhead to surface. 30 days.
Mechanical Conditions
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition,
inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Corrective Action: Comply w/ Rule 605.d. Date: 09/28/2018

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401748895	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4565917
691200392	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4565914