

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2018

Submitted Date:

09/06/2018

Document Number:

681701070**FIELD INSPECTION FORM**Loc ID 335902 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Prescott, Lorne	(970) 812-5311	lprescott@laramie-energy.com	
, Laramie		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>
Colby, Lou		lou.colby@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Spencer, Stan		stan.spencer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285254	WELL	AL	12/10/2009	LO	045-12408	CASCADE CREEK 697-4-54D	EI
285255	WELL	AL	12/10/2009	LO	045-12405	CASCADE CREEK 697-3-41D	EI
285256	WELL	AL	12/10/2009	LO	045-12406	CASCADE CREEK 697-4-29D	EI
285257	WELL	AL	12/10/2009	LO	045-12407	CASCADE CREEK 697-4-39D	EI
285258	WELL	AL	12/10/2009	LO	045-12404	CASCADE CREEK 697-3-25D	EI

**General Comment:**[COGCC Environmental inspection. Follow-up to Remediation Project #11426 for closure of Pit Facility #291970.](#)[At the time of inspection, there was no surface indication of pit. Excavation was present in the center of the pad had a cut and capped well in the center. Operator using facility to stage dozens of frac tanks, which did not have secondary containment berms. See photos.](#)[Contact COGCC EPS Steven Arauza to discuss open excavation and capped well.](#)

**Inspected Facilities**

Facility ID: <u>285254</u>	Type: <u>WELL</u>	API Number: <u>045-12408</u>	Status: <u>AL</u>	Insp. Status: <u>EI</u>
Facility ID: <u>285255</u>	Type: <u>WELL</u>	API Number: <u>045-12405</u>	Status: <u>AL</u>	Insp. Status: <u>EI</u>
Facility ID: <u>285256</u>	Type: <u>WELL</u>	API Number: <u>045-12406</u>	Status: <u>AL</u>	Insp. Status: <u>EI</u>
Facility ID: <u>285257</u>	Type: <u>WELL</u>	API Number: <u>045-12407</u>	Status: <u>AL</u>	Insp. Status: <u>EI</u>
Facility ID: <u>285258</u>	Type: <u>WELL</u>	API Number: <u>045-12404</u>	Status: <u>AL</u>	Insp. Status: <u>EI</u>

**Environmental****Spill/Remediation:**

Comment: Remediation Project #11429 was an approved workplan for pit closure. There was no sign of the subject pit on inspection date. Operator has not provided project update as of 9/6/2018

Corrective Action: Operator shall submit an eForm 27 Supplemental report to provide update to Remediation Project #11426.

Date: 09/30/2018

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
November 3, 2018 Field Inspection Report (doc #680102392) included corrective actions for operator to initiate reclamation in areas no longer required for operations, with instruction to complete reclamation activities by 6/15/2018. A copy of this inspection report will be sent to COGCC Reclamation Specialist Lou Colby.	arauzas	09/06/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681701083	20180829 Field Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4571625">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4571625</a>