

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/05/2018

Submitted Date:

09/07/2018

Document Number:

689401582

FIELD INSPECTION FORM

Loc ID 311744 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 SEVENTEENTH STREET #1400
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Laramie Energy LLC		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221631	WELL	SI	04/01/2018	GW	077-08233	HORSESHOE CANYON 2	WK

General Comment:

[This is a plugging inspection, any corrective actions not addressed from previous inspections are still applicable.](#)

Inspected Facilities

Facility ID: 221631 Type: WELL API Number: 077-08233 Status: SI Insp. Status: WK

Cement

Cement Contractor

Contractor Name: SPN Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): surface Cement Volume (sx): _____

Good Return During Job: YES Cement Type: G

Comment: (9/5/18) Form 42 Doc#401745329 received. Operator rep Troy on site. Perf @388'. Circulated 32 bbls. Pumped 160 sxs of cement. Dug up and cut off CSG 4' below ground level. Pumped 33 more sxs. Cement not to surface (9/6/18) Pumped 17 sxs top job. Cement to surface. Welded plate on.

Corrective Action: _____ Date: _____

Workover

Comment: SPN Rig 30 Workover rig for plugging

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689401584	Horseshoe Canyon 2 Plugging photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4572697