

Inspection Photos

Operator: XTO Energy

API: 05-067-05187

Date: 8/21/2018



Photo 1. View of beginning of transect 1 facing eastward.



Photo 2. Birdseye view of vegetation at the midpoint of transect 1, within the project disturbance.



Photo 3. View of transect 1, within the project disturbance facing westward from the end of the transect.



Photo 5. View of the beginning of transect 2, reference area, facing southward.



Photo 6. Birdseye view of vegetation at the midpoint of transect 2, within the reference area.