

Inspection Photos

Location Name: Cache - 66N63W / 8SWSE

Location #: 306312



Photo #1

Cache 8-34 (API 05-123-24412) wellhead.

No sign or emergency contact information

From previous FIR



Photo #2

Cache 8-34 wellhead.


Sign & Emergency contact number now posted



Inspection Photos

Location Name: Cache - 66N63W / 8SWSE

Location #: 306312



Colorado Oil & Gas Conservation Commission
40.49573, -104.45926, 1426.0m, 328°
2018/09/07 02:08:27 PM

Photo #3

Cache 8-34 wellhead.

Observed motor valve hissing & venting gas
Crew on site repaired valve. Venting ceased.



Colorado Oil & Gas Conservation Commission
40.49954, -104.4623, 1409.0m, 176°
2018/07/12 02:33:41 PM

Photo #4

Cache 8-34, 8-13, 8-23, 8-24, 8-33,

Cornish 8-53 Battery

From previous FIR



Inspection Photos

Location Name: Cache - 66N63W / 8SWSE

Location #: 306312



Photo #5

Compressor

Stained soil

From previous FIR



Photo #6

Compressor removed

Stained soil appears remediated



Inspection Photos

Location Name: Cache - 66N63W / 8SWSE

Location #: 306312



Colorado Oil & Gas Conservation Commission
40.49949, -104.46208, 1418.0m, 335°
2018/09/07 03:30:30 PM

Photo #7

Compressor

Moved while soil remediated



Colorado Oil & Gas Conservation Commission
40.49944, -104.46198, 1417.0m, 353°
2018/09/07 03:31:51 PM

Photo #8

East separator doghouse.

Trash – oily bucket



Inspection Photos

Location Name: Cache - 66N63W / 8SWSE

Location #: 306312



Colorado Oil & Gas Conservation Commission
40.49939, -104.46195, 1414.0m, 353°
2018/07/11 02:09:45 PM

Photo #9

East separator doghouse.

Trash – oily rag, oily bucket, old valve

From previous FIR



Colorado Oil & Gas Conservation Commission
40.4994, -104.46196, 1417.0m, 18°
2018/09/07 03:31:37 PM

Photo #10

East separator doghouse.

Trash – oily rag, oily bucket, old valve

