

Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



Photo #1

Federal Osprey 35-3 (API # 05-123-20272) wellhead

Bradenhead not plumbed to surface

From previous FIR



Photo #2

Federal Osprey 35-3 wellhead

Bradenhead not plumbed to surface

Vac-Truck clearing flowline leak downstream

Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



Photo #3

Federal Osprey 35-3 Battery

From previous FIR



Photo #4

Federal Osprey 35-3 Battery

Current View



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



Photo #5

Federal Osprey 35-3 (API # 05-123-20272) H2O tank

Berms dimensions appear inadequate for containment of vessel contents as referenced in previous FIR.



Photo #6

Federal Osprey 35-3 H2O tank

Berms dimensions now appear adequate

New capacity label & placard



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



Photo #7

Federal Osprey 35-3 Oil treater

Stained soil from previous FIR
remains apparent



Photo #8

Federal Osprey 35-3 Oil treater

Stained soil appears to have been remediated



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



Photo #9

Federal Osprey 35-3 behind oil tanks

Un-permitted pit referenced from previous FIR

Remains apparent



Photo #10

Federal Osprey 35-3 behind oil tanks

Un-permitted pit referenced from previous FIR

has been filled in



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



Photo #11

Federal Osprey 35-3 well anchors

1 - Un-marked anchor referenced from previous FIR
Remains apparent




Photo #12

Federal Osprey 35-3 well anchors

4 - anchors are now marked



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



Photo #13

Federal Osprey 35-3 Pumping Unit
Stain on gearbox from previous FIR
remains apparent



Photo #14

Federal Osprey 35-3 Pumping Unit
Stained gearbox & soil near pump jack base appear
to have been remediated

Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



Photo #15

Federal Osprey 35-3 Gas Engine – Prime Mover
Stained soil near gas engine base referenced from
previous FIR remains apparent



Photo #16

Federal Osprey 35-3 Gas Engine – Prime Mover
Stained soil near gas engine base appears to have
been remediated



Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



Photo #17

Federal Osprey 35-3 Gas Engine – Prime Mover

No engine muffler

referenced from previous FIR

Remains apparent



Photo #18

Federal Osprey 35-3 Gas Engine – Prime Mover

No engine muffler

Remains apparent

Stained soil - remediated



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



Photo #19

Federal Osprey 35-3 Pit

Weeds inside of pit netting



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources