

Inspection Photos  
Location Name: Neva Dove A #2  
API: 05-067-08412



95 bbl. produced water PBV.



Weeds present along southern edge of location.

Inspection Photos  
Location Name: Neva Dove A #2  
API: 05-067-08412



**Neva Dove A #2 production equipment.**



**Neva Dove A #2 well head and progressive cavity pump.  
Pump is leaking oil.**