

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
08/29/2018

Submitted Date:  
09/04/2018

Document Number:  
678301832

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: GINTAUTAS, PETER On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 42640  
Name of Operator: HYNDREX RESOURCES  
Address: 1531 4TH AVE  
City: GREELEY State: CO Zip: 80631-

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

| Contact Name      | Phone        | Email                      | Comment                         |
|-------------------|--------------|----------------------------|---------------------------------|
| Binschus, Chris   |              | chris.binschus@state.co.us |                                 |
| ,                 |              | cogcc@kpk.com              | <a href="#">All Inspections</a> |
| Lara-Mesa, Susana | 303-825-4822 | cogcc@kpk.com              | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type             | Status | Status Date | Well Class | API Num | Facility Name       | Insp Status |
|-------------|------------------|--------|-------------|------------|---------|---------------------|-------------|
| 455229      | SPILL OR RELEASE | CL     | 07/02/2018  |            | -       | SPILL/RELEASE POINT | EI          |

**General Comment:**

inspection as part of soil sampling by COGCC staff in response to complaint 200446145, Corrective actions in this inspection are in addition to those listed in 682403895

**Location**

Overall Good:

**Signs/Marker:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | OTHER   |       |            |
| Comment:           | Flowline/crude oil transfer line crosses public right of way or utility easement but is not marked or is not marked per rule 1102.g.2.  |       |            |
| Corrective Action: | Install markers that identify the location of flowlines or crude oil that identify the location of the flowline or crude transfer line following language per Rule 1102.g.(2) | Date: | 10/04/2018 |

**Emergency Contact Number:**

|                    |                      |       |                      |
|--------------------|----------------------|-------|----------------------|
| Comment:           | <input type="text"/> | Date: | <input type="text"/> |
| Corrective Action: | <input type="text"/> |       |                      |

**Good Housekeeping:**

|                    |  |       |                      |
|--------------------|--|-------|----------------------|
| Type               | UNUSED EQUIPMENT   |       |                      |
| Comment:           | unused equipment (dozer) noted in 682403895 has been removed |       |                      |
| Corrective Action: |  | Date: | <input type="text"/> |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

|                    |  |       |                      |
|--------------------|--|-------|----------------------|
| Yes/No             |  |       |                      |
| Comment:           |  |       |                      |
| Corrective Action: |  | Date: | <input type="text"/> |

**Flaring:**

|                    |  |       |                      |
|--------------------|--|-------|----------------------|
| Type               |  |       |                      |
| Comment:           |  |       |                      |
| Corrective Action: |  | Date: | <input type="text"/> |

**Inspected Facilities**

Facility ID: 455229 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

**Complaint**

Comment: [in response to complaint 200446145](#)

Corrective Action:

Date:

**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER Estimated Spill Volume: \_\_\_\_\_

Comment: spill of produced water with some oil reported as spill 455229

Corrective Action: submit map of locations of soil samples collected as part of initial spill response. Analytical data was received previously. Submit manifest records of any impacted soils removed during initial response Date: 09/11/2018

Reportable: YES GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: Other Comment: soil samples in crop field where spill occurred.

**Sample** Sample Type: SOIL COMPOSITE

Time: \_\_\_\_\_ (MM/dd/yyyy hh:mm) GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

BTEX: \_\_\_\_\_ TPH: YES Anion: \_\_\_\_\_ Captions: \_\_\_\_\_ General Chemistry: \_\_\_\_\_

Dissolved Methane: \_\_\_\_\_ Composition: \_\_\_\_\_ Stable Isotopes: \_\_\_\_\_ 8260: \_\_\_\_\_

8270: \_\_\_\_\_ RCRA Metals: \_\_\_\_\_ 910-Metals: YES PAH: \_\_\_\_\_

Other: Saturated paste SAR, EC, pH

Comment: see attached aerial images with locations of 10 sites sampled, including 2 background samples. 8 samples along east-west line were composites of three samples across approximately 30feet north to south centered on line.

**Lab:**

Lab Name \_\_\_\_\_

ALS Fort Collins

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                                      | URL   |
|--------------|--|---|
| 401752588    | INSPECTION SUBMITTED                             | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4569055">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4569055</a> |
| 678301835    | area of spill 455229 in 2017 aerial image        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4569047">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4569047</a> |
| 678301836    | spill 455229 COGCC sampling on 2017 aerial image | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4569048">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4569048</a> |