

Inspection Photos

Operator: BP Production

API: 05-067-08507

Date: 9/10/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation is progressing with grasses and shrubs such as crested wheatgrass (*Agropyron cristatum*), smooth brome (*Bromus inermis*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 4. View of erosional channel forming within the eastern project area.