

**Inspection Photos**  
**Location Name: RUSSELL, TOM E. UNIT D 2**  
**Facility ID: 241030**



**Photo 1. Wellhead**



**Photo 2. Fluid leaking from pumpjack gear box**

**Inspection Photos**  
**Location Name: RUSSELL, TOM E. UNIT D 2**  
**Facility ID: 241030**



Colorado Oil & Gas Conservation Commission  
40.10424, -104.94424, 1490.0m, 172°  
2018/09/11 13:28:33

**Photo 1. Wellhead**

