

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/21/2018

Submitted Date:

09/05/2018

Document Number:

688800271

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 1050 17TH STREET SUITE 2500
City: DENVER State: CO Zip: 80265

Findings:

- 7 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Walter, Kyle		kwalter@enduringresources.com	All Inspections
Pohl, April	505-444-0520	apohl@enduringresources.com	All Inspections Southwest
McDaniel, James	505-444-3004	jmcdaniel@enduringresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456707	SPILL OR RELEASE	AC	09/04/2018		-	Federal 3-1 Pipeline	EI

General Comment:

On August 21, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of Spill/Release Point ID #456707. For more information regarding this release of produced water, discovered on 8/21/18, please refer to document #401745169. Enduring Resources representative Kyle Walter was on site during this inspection.

Location

Lease Road:			
Type	Access		
comment:	Release point is near access to SE Durango Federal 4-1.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 80%;" type="text"/>
Corrective Action:	<input style="width: 80%;" type="text"/>
	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 456707 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental**Spills/Releases:**Type of Spill: PRODUCED WATEREstimated Spill Volume: 50Comment: For more information regarding this release, please refer to document #401741023.Corrective Action: Operator shall submit a Form 27 Site Investigation and Remediation Workplan addressing elevated contaminants of concern at the release point.Date: 10/05/2018Reportable: YESGPS: Lat 37.234600Long -107.845800

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment	User	Date
<p>On August 21, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of Spill/Release Point ID #456707. For more information regarding this release of produced water, discovered on 8/21/18, please refer to document #401745169. Enduring Resources representative Kyle Walter was on site during this inspection. Reportedly a 4" poly gathering line was the source of the release. A One Call had been ordered prior to excavation of the pipeline. The release was discovered by the lease operator on 8/21/18. Enduring Resources employees had taken water and soil samples from the impacted area.</p> <p>An M and R Trucking water truck was removing the standing water from the low lying area. The water was to be taken to an Enduring Resources injection facility for disposal. The pool of water was approximately 25' by 60'.</p> <p>Sample results indicate elevated SAR values in the impacted area. The operator shall submit a Site Investigation and Remediation Workplan to address this Table 910-1 exceedance. The proposed work plan shall include documentation of land owner approval (BLM).</p>	hughesj	09/05/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401754557	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4570619
688800272	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4570618