

Inspection Photos
Location Name: Federal Sandwash 2-1
API: 05-081-06792



Photo 1. Overview of location taken at entrance facing east.



Photo 2. Incorrect emergency contact information on location signs.

Inspection Photos
Location Name: Federal Sandwash 2-1
API: 05-081-06792



Photo 3. Corrosion on tank.



Photo 4. Hole in tank from corrosion.

Inspection Photos
Location Name: Federal Sandwash 2-1
API: 05-081-06792



Photo 5. Hole in tank from erosion.



Photo 6. Methanol container labeled as 500 BBL capacity.

Inspection Photos
Location Name: Federal Sandwash 2-1
API: 05-081-06792



Photo 7. Incorrect emergency contact information on location signs.



Photo 8. Incorrect emergency contact information on location signs.