

Inspection Photo
Miller 42A-36-692
API # 045-17621
Inspection # 689301896



Location Photo #1



Location Photo #2

**Inspection Photo
Miller 42A-36-692
API # 045-17621
Inspection # 689301896**



Location Photo #3



**Location Photo #4, unmarked anchors on
west side of wellheads**

**Inspection Photo
Miller 42A-36-692
API # 045-17621
Inspection # 689301896**



Location Photo #5, unmarked anchors on west side of wellheads



Location Photo #6, unmarked anchors on east side of wellheads.

**Inspection Photo
Miller 42A-36-692
API # 045-17621
Inspection # 689301896**



Location Photo #7, unmarked anchors on east side of wellheads.



Location Photo #8, unmarked anchors on east side of wellheads.

**Inspection Photo
Miller 42A-36-692
API # 045-17621
Inspection # 689301896**



Location Photo #9, unmarked anchors on east side of wellheads.