

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2018

Submitted Date:

09/12/2018

Document Number:

688000198**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
400319 \_\_\_\_\_ YOUNG, ROB \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 14855Name of Operator: CENTRAL OPERATING INCAddress: 1600 BROADWAY STE 1050City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email                         | Comment        |
|--------------|-------|-------------------------------|----------------|
| Potter, Gail |       | centraloperatinginc@gmail.com | Office manager |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|---------|---------------|-------------|
| 117704      | PIT  | AC     | 09/23/1999  |            | -       | MARICK "C"    | AC          |

**General Comment:**[Environmental inspection related to Rem #9799.](#)

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 117704Lat: 39.824343Long: -103.183509Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: 

Former oil skim pit has been excavated and impacted soil largely removed. Impacted soil visible in the west wall of the former oil skim pit shared with the produced water pit. Shared wall will require removal.

Corrective Action: 

Provide available soil sample analytical data, soil disposal manifests on a supplemental eForm 27.

Date: 09/28/2018c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 688000199    | Location photographs | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4577472">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4577472</a> |