

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/06/2018

Submitted Date:

09/13/2018

Document Number:

691300506**FIELD INSPECTION FORM**Loc ID 333083 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10312Name of Operator: PROSPECT ENERGY LLCAddress: 1036 COUNTRY CLUB ESTATES DRCity: CASTLE ROCK State: CO Zip: 80108**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Giltner, Ward		wgiltner@yahoo.com	
Twele, Megan		mtwele@progressivepcs.net	
Adamczyk, Megan		megan.adamczyk@state.co.us	
Griggs, Mary	(303)-912-8292	mary.griggs@memorialrd.com	Manages Prospect Energy
Martin, Dene		dmartin@memorialrd.com	Send inspections to Anthony as well

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450992	UIC WATER TRANSFER STATION	AC	06/06/2017		-	Water Plant 450992	AC

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

Paint

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	500 BBLS	STEEL AST		,	
Comment:	Tanks on the water injection facility are in need of repair or replacement. Strong odors are occurring on and off location as a result. See complaint portion of this inspection for further details.					
Corrective Action:	Comply with rule 605.d				Date:	11/14/2018

Paint

Condition	Adequate	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	

Inspected Facilities

Facility ID: 450992 Type: UIC WATER API Number: - Status: AC Insp. Status: AC

Complaint

Comment: Inspection in response to complaint. 18#200446243

Field Inspector Assigned: Adam Kraich

Complaint Received:

Date: 9-12-2018

Complaint Contacted:

Date: 9-12-2018 @14:57. Left VM, no callback.

Location #: 333083

Inspection Document #: 691300506

Nature of complaint: Odor

Field Inspector Actions:

On 9-12-2018, I received a complaint in regard to odor coming from the MSSU (Muddy Sand Stone Unit) location operated by Prospect Energy.

On 9-12-2018, I performed a site inspection of the location. The location is utilizing enhanced recovery by way of injecting produced water into their respective formations. I did experience an odor at the facility, the odor was consistent with that of produced brine water. After speaking with the operator, it has been determined that the odor is originating from the bulk water storage tanks at the injection facility. Additionally, I tested the injection area with a 4 gas monitor as well as a dedicated H2S monitor to ensure odors were not hazardous.

As odors are traveling off location, I have issued a corrective action 805.b to the operator, however, mitigation of the issue will require heavy equipment and pre job safety planning, and as such the corrective action date will be extended to accommodate these processes.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691300507	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4578032