

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/21/2018

Submitted Date:

09/07/2018

Document Number:

680603045**FIELD INSPECTION FORM**
 Loc ID 333793 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 56680Name of Operator: MERRION OIL & GAS CORPAddress: 610 REILLY AVENUECity: FARMINGTON State: NM Zip: 87401**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name      | Phone | Email                | Comment                         |
|-------------------|-------|----------------------|---------------------------------|
| Thompson, Philana |       | pthompson@merrion.bz | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 285806      | WELL | PR     | 06/29/2007  | GW         | 067-09209 | BETELGEUSE 1  | RI          |
| 292295      | WELL | PR     | 11/24/2009  | GW         | 067-09391 | RIGEL 1       | RI          |

**General Comment:**

This is an interim reclamation and stormwater inspection. A field inspection was conducted on August 21, 2018 and followed up with a database review on September 7, 2018. Any corrective actions not addressed from previous inspections are still applicable.

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 285806 | Type: | WELL | API Number: | 067-09209 | Status: | PR | Insp. Status: | RI |
|                      |        |       |      |             |           |         |    |               |    |
| Facility ID:         | 292295 | Type: | WELL | API Number: | 067-09391 | Status: | PR | Insp. Status: | RI |
|                      |        |       |      |             |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Project area is surrounded by an irrigation channel and associated wetland vegetation, as well as sagebrush shrubland. Revegetation is progressing within the interim reclamation areas.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment Green kochia weeds are growing around fired equipment.Corrective Action Kochia weeds will dry and become debris. Control weeds around fired equipment.Date **10/12/2018**Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

|  |   |
|--|---|
| Date Final Reclamation Started: _____  | Date Final Reclamation Completed: _____   |
| Final Land Use: _____  |   |
| Reminder: _____  |   |
| Comment: <div style="border: 1px solid black; height: 30px; width: 100%;"></div>           |   |
| Well plugged _____   | Pit mouse/rat holes, cellars backfilled _____   |
| Debris removed _____   | No disturbance /Location never built _____  |
| Access Roads _____   | Regraded _____  |
|  | Contoured _____   |
|  | Culverts removed _____  |
|  | Gravel removed _____  |
| Location and associated production facilities reclaimed _____                              | Locations, facilities, roads, recontoured _____   |
| Compaction alleviation _____   | Dust and erosion control _____  |
| Non cropland: Revegetated 80% _____  | Cropland: perennial forage _____  |
| Weeds present _____  | Subsidence _____  |
| 1004.d. FINAL VEGETATION TRANSECT  |   |
| TRANSECT RESULTS OF DISTURBED AREA% _____  |   |
| TRANSECT RESULTS OF REFERENCE AREA% _____  |   |
| TOTAL % OF DESIRABLE VEGETATION COVER _____  |   |
| VEGETATIVE COVER _____   |   |
| Comment: <div style="border: 1px solid black; height: 30px; width: 100%;"></div>           |   |
| Corrective Action: <div style="border: 1px solid black; height: 30px; width: 100%;"></div> | Date _____  |
| Overall Final Reclamation _____  | Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/> |

**Storm Water:**

| Loc Erosion BMPs  | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment          |
|---|-----------------|-------------------------|-----------------------|---------------|--------------------------|------------------|
|   |                 |                         |                       |               |                          |                  |
| Comment: <a href="#">Erosion is occurring along the access road where it appears that surface flows are eroding the road surface and carrying sediment downslope toward a nearby drainage. See attached photos.</a> |                 |                         |                       |               |                          | Date: 10/08/2018 |
| Corrective Action: <a href="#">Install stormwater controls to stabilize erosion and sediment transport along the access road.</a>   |                 |                         |                       |               |                          |                  |
| <b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT   |                 |                         |                       |               |                          |                  |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401757228    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573491">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573491</a> |
| 680603046    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573488">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573488</a> |