

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/07/2018

Submitted Date:

09/07/2018

Document Number:

691200423**FIELD INSPECTION FORM**
 Loc ID 309871 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294561	WELL	SI	02/01/2018	GW	123-25496	CACHE 8-54	SI
417623	WELL	SI	05/01/2018	GW	123-31704	NEW CACHE 8-43	SI

General Comment:[This is a WELL Inspection.](#)[This FIR is a Follow-up inspection to FIR #684905429 dated 5/18/2018 & FIR #691200276 dated 7/19/2018.](#)

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Contact Phone number has been posted at New Cache 8-43 & Cache 8-54 wellheads. This resolves the CA from previous FIRs #691200276 dated 7/19/2018 & #684905429 dated 5/18/2018. New Cache 8-43 is adjacent to Cache 8-54 therefore signage on New Cache 8-43 is sufficient.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	No sign posted at battery. Failed to comply with CA from FIRs #684905429 & #691200276. CA date will remain the same from previous FIR #684905429.		
Corrective Action:	Install sign to comply with rule 210.b. CA date will remain the same from previous FIR #684905429.		Date: 07/18/2018
Emergency Contact Number:			
Comment:	Emergency contact number now posted at both wells. This resolves the CA from FIR #691200276 dated 7/19/2018.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	New Cache 8-43 has iron panel fence. Cache 8-54 has iron panel fence.		
Corrective Action:			Date:
Type			
Comment:	Refer to previous FIR #691200274 for additional fencing info.		
Corrective Action:			Date:
Equipment:			
Type:	#		corrective date
Comment:	Refer to previous FIR #691200274 for additional equipment info.		
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.495350,-104.454770	
Comment:	This centralized battery serves 2 locations (310877, 309871). Refer to previous FIR #691200274 for Tanks & Berms info.					
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 294561 Type: WELL API Number: 123-25496 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI. Well is shut-in at separator.

Corrective Action: _____

Date: _____

BradenHeadComment: Bradenhead appears plumbed to surface.

Corrective Action: _____

Date: _____

Facility ID: 417623 Type: WELL API Number: 123-31704 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI. Well is shut-in at separator.

Corrective Action: _____

Date: _____

BradenHeadComment: Bradenhead appears plumbed to surface.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401757068	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573286
691200424	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4573279