

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/10/2018

Submitted Date:

09/11/2018

Document Number:

678301837**FIELD INSPECTION FORM**Loc ID 336207 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
,		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451374	TANK BATTERY	AC	08/27/2014		-	Coors V 6-13 battery	EG

**General Comment:**

on location 07:45 to 14:10, produced water tank removed during inspection, flowlines between separator, ECD area to south of fenced battery and connecting to PW vessel and to area where crude tank had previously been were pulled from ground

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: signs removed from location at end of work day

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	observed trash, fencing removed from around wells and battery and work equipment no longer in use being loaded onto contractor trucks throughout day		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			
Crude Oil	Tank	<= 1 bbl			
Comment:	from visual and olfactory observation an approximately 4-5 inch thick liquid hydrocarbon impacted soil zone directly beneath partly buried fiberglass PW vessel was observed. Contractor excavated and set aside the approximately 1 cubic yard of impacted soil at surface which was subsequently removed by truck under manifest for disposal off site. my estimation is that spill volume was less than 1 barrel of product and thus not reportable by form 19. See attached photos of excavation, soils and sampling area at base				
Corrective Action:	submit results on confirmation soil sampling as supplemental form 27 for project 11666.			Date:	12/10/2018

In Containment: No

Comment: sampling of soil from sidewalls and base of excavation were done by contractor to operator for Table 910-1 analytes.

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	fencing around removed during course of day and loaded onto contractor trailers for removal from site		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,	
Comment:	removed during course of day per approved site investigation and remediation plan project 11666 as shown in attached photos					
Corrective Action:					Date:	

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient		Adequate

Comment:	around PW tank area removed during course of day		
Corrective Action:		Date:	
<b><u>Venting:</u></b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 451374    Type: TANK    API Number: -    Status: AC    Insp. Status: EG

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401759494	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4575473">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4575473</a>
678301838	1. PW vessel before removal	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4575457">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4575457</a>
678301839	2. flowline removal	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4575458">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4575458</a>
678301840	3. PW vessel after removal	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4575459">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4575459</a>
678301841	4. sampling zone at base of PW vessel excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4575460">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4575460</a>
678301842	5. base of excavation with most impact soil removed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4575461">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4575461</a>
678301843	6. soils visible after PW vessel removal	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4575462">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4575462</a>