

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401688098
Date Received:
06/28/2018

FIR RESOLUTION FORM

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87415
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

| Contact Name | Phone | Email |
|-----------------|-------|---------------------------------|
| Rowley, Darren | | drowley@logosresourcesllc.com |
| Sessions, Tamra | | tsessions@logosresourcesllc.com |

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602721
Inspection Date: 05/17/2018 FIR Submit Date: 06/04/2018 FIR Status:

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC Company Number: 10679
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 326449

Location Name: IGNACIO 33-8-N33N8W Number: 12NWNE County: LA PLATA
Qtrqtr: NWNE Sec: 12 Twp: 33N Range: 8W Meridian: N
Latitude: 37.122980 Longitude: -107.663920

FACILITY - API Number: 05-067-00 Facility ID: 216513

Facility Name: IGNACIO 33-8 Number: 001C
Qtrqtr: NWNE Sec: 12 Twp: 33N Range: 8W Meridian: N
Latitude: 37.122980 Longitude: -107.663920

CORRECTIVE ACTIONS:

1 CA# 116644

Corrective Action: Thistles will need to be treated this year where rosettes observed. Seeds will remain viable for 10-15 years and therefore, subsequent monitoring and treatment will be needed. Date: 06/30/2018

Response: CA COMPLETED Date of Completion: 06/18/2018

Operator Comment: LOGOS Operating sprayed for weeds within the project area. We were unable to locate any rosettes within our area of disturbance. The identified musk thistles in photo 2 are on the land owners property. Logos Operating does not have surface owner's permission to spray in this area. Please see attached photos of weed spraying.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 CA# 116645

Corrective Action: Stormwater controls are needed to de-energize stormwater flows exiting the southern project area. Successful revegetation within the unused portions of the southwestern well pad will help stabilize erosion here. This will be required during fall 2018 seeding window as described above, if vegetation cover is not increasing during the 2018 growing season.

Date: 07/06/2018

Response: CA COMPLETED

Date of Completion: 06/18/2018

Operator Comment: Storm water controls have been installed to de-energize storm water flows from the project area. Unused areas of the project area have been seeded (please see photos included)and these areas will continue to be monitored for vegetation growth and managed as needed.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see the attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Larissa Farrell

Signed: _____

Title: Environmental Technician

Date: 6/28/2018 8:47:31 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|-------------------------------|---------------------------|
| 401688098 | FIR RESOLUTION SUBMITTED |
| 401688121 | Photo |
| 401688122 | Photo |
| 401688123 | Photo |
| 401688124 | Photo |
| 401688125 | Photo |
| 401688126 | Photo |

Total Attach: 7 Files