

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2018

Submitted Date:

09/13/2018

Document Number:

691200450**FIELD INSPECTION FORM**Loc ID 317523 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96155Name of Operator: WHITING OIL & GAS CORPORATIONAddress: 1700 BROADWAY STE 2300City: DENVER State: CO Zip: 80290**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|-------|----------------------------------|---------------------|
| | | dnr_cogccengineering@state.co.us | |
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| , | | WhitingEasternCO@Whiting.com | Eastern Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 238910 | WELL | SI | 06/01/2014 | OW | 123-05787 | NELSON RANCHES 1 | TA |

General Comment:This is a WELL Inspection. Did not inspect decommissioned battery site.

Location

| | | | |
|--------------------|----------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------|--|-------------|
| Emergency Contact Number: | | |
| Comment: | | |
| Corrective Action: | | Date: _____ |

| | | | |
|---------------------------|--|-------|--|
| Good Housekeeping: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Barbed wire | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | Observed stained soil underneath wellhead piping. Remove or remediate stained soil. Mechanical Conditions Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. (30 Days). | | |
| Corrective Action: | Comply with Rule 605.d. | Date: | 10/15/2018 |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | 4/4-marked | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------|-----|--|--|
| Venting: | | | |
| Yes/No | YES | | |

| | | | |
|--------------------|--|-------|------------|
| Comment: | Observed 2" connection-union venting - leaking dry gas. This is the horizontal union located between well master valve & closed motor valve. Notified Whiting Petroleum of this condition by telephone (800-723-4608). Spoke with Katie Anderson and discussed the situation and advised that they correct the issue within 24 hours to ensure that venting has ceased. Call was made at 12:00PM on Thursday 09/13/2018. Mechanical Conditions. (1-Day if active leak) | | |
| Corrective Action: | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Comply with Rule 605.d. | Date: | 09/14/2018 |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 238910 Type: WELL API Number: 123-05787 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Well appears to be in TA status. Wellhead is set up for plunger lift with wellhead tree bull plugged downstream of motor valve.
Records indicate last production was 05/2014.
Did NOT find records indicating an MIT has been performed.
Mechanical Integrity Testing (Temporarily Abandoned Wells). Rule 326.c
No current MIT on record or delinquent as required by Rule 326 (10 Days)

Corrective Action: Comply with Rule 326. Contact dnr_cogccengineering@state.co.us with resolution plan.Date: 09/24/2018**BradenHead**Comment: Bradenhead does appear plumbed to surface.Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401762519 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4578433 |
| 691200451 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4578430 |
| 691200452 | Union venting video | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4578431 |