

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/14/2018

Submitted Date:

09/14/2018

Document Number:

689401618**FIELD INSPECTION FORM**

| | | | | |
|--|------------------------------------|---|-------------------|---|
| Loc ID 334433 | Inspector Name: CONKLIN, CURTIS | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 12 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested |
| Operator Information: OGCC Operator Number: <u>10433</u> Name of Operator: <u>LARAMIE ENERGY LLC</u> Address: <u>1401 SEVENTEENTH STREET #1400</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u> | | | | |
| | | | | |
| | | | | |

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|-------|---------------------------------------|---------------------------------|
| Laramie Energy LLC | | cogccnotifications@laramie-energy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 297214 | WELL | PR | 03/10/2011 | GW | 077-09685 | NVEGA 22-121 | PR |
| 297608 | WELL | PR | 02/24/2011 | OG | 077-09695 | NVEGA 22-124 | PR |
| 297609 | WELL | PR | 04/10/2014 | GW | 077-09696 | NVEGA 21-331 | PR |
| 297610 | WELL | AL | 05/19/2016 | LO | 077-09697 | NVega 22-134 | AL |
| 297611 | WELL | PR | 05/15/2010 | OG | 077-09698 | NVEGA 22-131 | PR |
| 297613 | WELL | AL | 02/05/2009 | LO | 077-09700 | NVEGA 21-334 | AL |
| 297614 | WELL | PR | 04/21/2014 | GW | 077-09701 | NVega 21-431 | PR |

General Comment:

This is a follow up inspection to FIR Doc#689401526. Any corrective actions not addressed from previous inspections are still applicable.

LocationOverall Good: ☒

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Nearest public access not listed on sign | | |
| Corrective Action: | Comply with Rule 210 | Date: | 10/15/2018 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Posted Emergency Contact Number 1-800-891-6191

Corrective Action:

Date:

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| METHANOL | 1 | <50 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|--------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 3 | 400 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

| | |
|------------------|--|
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297214 | Type: | WELL | API Number: | 077-09685 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR w/ Plunger | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297608 | Type: | WELL | API Number: | 077-09695 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR w/ Plunger | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297609 | Type: | WELL | API Number: | 077-09696 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR w/ Plunger | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297610 | Type: | WELL | API Number: | 077-09697 | Status: | AL | Insp. Status: | AL |
| Workover | | | | | | | | | |
| Comment: | Conductor is no longer visible at surface. Corrective action from previous inspection has been met. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297611 | Type: | WELL | API Number: | 077-09698 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR w/ Plunger | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297613 | Type: | WELL | API Number: | 077-09700 | Status: | AL | Insp. Status: | AL |
| Workover | | | | | | | | | |
| Comment: | Conductor is no longer visible at surface. Corrective action from previous inspection has been met. | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 297614 | Type: | WELL | API Number: | 077-09701 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR w/ Plunger | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [Stormwater erosion appears to be controlled on the location at this time.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401763846 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4579576 |
| 689401619 | NVega 2A Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4579574 |