

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/14/2018

Submitted Date:

09/14/2018

Document Number:

689401620**FIELD INSPECTION FORM**
 Loc ID 334554 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Arauz, Steven		steven.arauza@state.co.us	
Laramie Energy LLC		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259437	WELL	PR	09/13/2002	GW	077-08730	BUZZARD CREEK 15-10	PR
262735	WELL	PR	04/01/2018	GW	077-08754	BUZZARD CREEK 15-16	PR

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable. For the most recent environmental inspection report of this facility, please refer to Doc#681701040

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Labels on chemical storage tanks are faded and not legible.		
Corrective Action:	Comply with Rule 210	Date:	10/15/2018
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank battery		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted Emergency Contact Number 1-800-891-6191

Corrective Action:

Date:

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused flowline risers at former produced water and condensate tank batteries have not been removed. Original corrective action and date still apply. See photos.		
Corrective Action:	Comply with Rule 603.f. (unused flowline risers)	Date:	08/18/2018
Type	TRASH		
Comment:	Trash appears to have been picked up at time of inspection. Corrective action from previous inspection has been met.		
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:	Chemical storage tank has been put in containment. Corrective action from previous inspection has been met.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Unused tanks remain on location. Original corrective action and date still apply.		
Corrective Action:	Comply with Rule 603.f. (unused equipment)	Date:	10/18/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: Stained soil mentioned on previous inspection was not visible at time of inspection. Corrective action from previous inspection has been met.

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		

Comment:	Panels		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLS	STEEL AST		,
Comment:	Condensate tank battery at SW corner of location. Two (2) out of four (4) condensate ASTs have been marked 'Out of Service,' as indicated in previous FIRs. Original corrective action and date still apply.				
Corrective Action:	Comply with Rule 603.f. (condensate ASTs)				Date: 10/18/2018

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLS	STEEL AST		,
Comment:	Produced water ASTs have been removed from service and are currently being stored at north end of location. See photos. Original corrective action and date still apply.				
Corrective Action:	Comply with Rule 603.f. (unused PW tanks)				Date: 10/18/2018

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
------	--

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 259437 Type: WELL API Number: 077-08730 Status: PR Insp. Status: PR**Producing Well**Comment: PR w/ plunger

Corrective Action:

Date:

Facility ID: 262735 Type: WELL API Number: 077-08754 Status: PR Insp. Status: PR**Producing Well**Comment: PR w/ plunger

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: Stormwater erosion appears to be controlled on the location at this time.						Date: _____
Corrective Action: _____						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments

Comment	User	Date
Follow up inspection required by environmental staff to address Remediation Project #11476.	conklinc	09/14/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401763898	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4579714
689401621	BCU 150 Pad Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4579709